

SEACOMP

PRODUCT CHANGE NOTIFICATION (PCN)

| | |
|--|----------------------------------|
| PCN NUMBER PCN19002 | DATE November 20, 2019 |
| CUSTOMER(S) ALL CUSTOMERS | |
| PROJECT(S) AFFECTED Displaytech standard items: DT022CTFT & DT022CTFT-TS | |
| EFFECTIVE DATE / OTHER REFERENCE • November 20, 2019 | |

DESCRIPTION OF CHANGE(S)

REASON FOR THE CHANGE(S)

Correct specification pinout. Pins #7 and #8 were swapped.

BEFORE CHANGE(S)

1. Pinout table on specification (page 4 & 5)
 - a. Pin #7 was HSYNC
 - b. Pin #8 was VSYNC

AFTER CHANGE(S)

1. Pinout table on specification (page 4 & 5)
 - a. Pin #7 is VSYNC
 - b. Pin #8 is HSYNC

Thank you for your continued interest in SEACOMP products and services. For additional assistance or questions, please contact SEACOMP Customer Service at sales@seacomp.com or the sales contact you are working with.

Sincerely,
For and on behalf of SEACOMP



Cy Johnson
Director of Engineering

